

Crowcon Technical Note

Document Reference: GEN087
Document applies to: 70X-V Oxygen Sensor
Release Date: 1st November 2018
Subject: Storage Shorting Link



The manufacturer of the **70X-V** Oxygen Sensor (**Crowcon Part Number: E01488/A**) has advised that, as of 1st November 2018, they will no longer be fitting the storage shorting link to the sensor pins in the factory.



70X-V with Link Fitted



70X-V with no Link Fitted

This means that when this spare sensor is fitted into a detector, it will require 2-4 hours of stabilisation time before it can be calibrated.

(If the sensor is supplied pre-fitted on a sensor module, a stabilisation time may still be required, but should be considerably less than for a sensor on its own).

Please note that when replacing sensors on products which use sensor modules (For Example: Xgard, TriplePlus+, Detective+), only the appropriate complete 'Replacement Sensor Module' should be used.

For more information please contact +44 (0)1235 557711, customersupport@crowcon.com