

Crowcon Technical Note

Document Reference: GEN090 – Notice of Obsolescence – mercaptan sensors
Document applies to: Xgard IQ, Xgard Type 1
Release Date: 18/02/2019

Affected Products: Xgard IQ & Xgard Type 1 mercaptan

Part Numbers: XIQ-ME, S013068/S and XGARD1-0765

Unfortunately, due to supply issues, the sensor used for the detection of mercaptan is no longer available. This sensor has previously been offered for use in Xgard Type 1 and XgardIQ

At this time we have been unable to source an equivalent sensor, therefore as of the 8th February 2019, we are unable to offer spare sensors or new product utilising this sensor.

For more information please contact +44 (0)1235 557711, customersupport@crowcon.com